NAME [illegible] CR-9 STRUCT. SETTING

LOCATION Rural DESCRIBED BY: Bo

DATE 29 Jan

UNIT 4.53 m



177 m
Mulinia valves scattered

177 m

branching vertical [illegible] burrows (sm
scattered Mulinia [illegible]

Rafted organics
Mottling possibly caused by bioturbation

SSD

SSD

SSD; [illegible] laminae

LOCATION _____ DESCRIBED BY: [illegible]

DATE 29 Jan.

UNIT 3-39M



sand lithoclast? SSD

SSD

sand lenses are rippled SSD

contacts of sand bases are sharp/probably not scour

250 μ

heavy mineral laminae 250 μ sand

Run 3 is a Rip of lower 0.85 m in Run 2

Sampled At
Run 1 - 0.15 m
Run 2 - 3.25 m